

Cleaning guidelines for Stonex quartz screed Surface

Sliptech has been working with Flex Flooring for a number of years offering extensive experience in the cleaning and maintenance of their floors.

To maintain a safe floor and keep the aesthetic appearance, it is essential that the floor is cleaned at regular intervals, depending on surface soiling. Please observe the following guidelines:

Equipment

It is essential that the cleaning equipment is maintained on a regular basis. Dirty cleaning equipment and unmaintained machinery can lead to dirt residues building up on the surface.

Safety

Maintenance is essential on all wet surfaces. If body fats or surface residues are allowed to build up this can negate the floors natural slip resistance and cause slip issues.

Daily Maintenance

The area should be cleaned over with a scrubber dryer filled with clean water assuring at least 2 passes in each direction

1 to 2 times a week (depending on traffic)

A solution of Ultra-Clean or PH neutral cleaner (no foam) should be applied using a soft broom or low pressure sprayer (20 parts water to 1 part cleaner) and left to soak for 3 minutes. Agitate whole area using a scrubber dryer filled with clean water, operating with water and vacuum off and then repeat with water and vacuum on. This procedure will ensure the removal of body fats and surface soiling from constant pedestrian traffic and remove any detergent residues. It is important that all residues are removed and disposed of in waste water drains, to avoid contamination of pool water.

Once a fortnight (or as required)

A solution of Commando or similar de-greaser/water softener (50 parts water to 1 part Commando) degreaser should be applied to the surface using a soft broom or low pressure sprayer. Leave on the surface for around 3 minutes, and then agitate once using a scrubber dryer with vacuum and water off and then repeat with water and vacuum on, ensuring that all detergent residues have been removed. Rinse off thoroughly using a minimum of 2 passes to ensure that all residues have been removed.

Deep cleaning (Quarterly)

Calcium deposits build-up over a period of months, this should be removed with Scalcon or a similar de-calcifier. Apply a strong solution of calcium cleaner (1 part Scalcon to 10 parts water). Leave on the surface for around 3 minutes whilst scrubbing using soft bristled broom, remove all residues using a scrubber dryer with water and vacuum on. Rinse off thoroughly using a minimum of 2 passes to ensure that all residues have been removed.

NOTES: If residues are not removed on a regular basis they will polymerise to the surface and become an effective agent, which will regenerate creating a slippery surface when exposed to moisture (i.e. spillages, wet footwear etc.)

Annual and periodic cleaning

For stubborn stains a professional service may be required. For all maintenance questions please contact Sliptech on 01206 826788 or info@sliptech.co.uk



Recommended Products:

Ultra Clean £25.31 + VAT. Commando £27.86 +VAT, Scalcon £28.71 + VAT
(Minimum order of 10 Litres per order)

All products used on site by Sliptech are available to buy either online www.sliptech.co.uk
or by emailing sales@sliptech.co.uk.